Sample Number	Type of Sample	Location of Sample	Asbestos Content
	Ambient Samp	ling Event January 25, 2011	
	Ambien	t Project# 101214AB	
003-01	Mudded Fitting	Kitchen 2 nd Floor	NAD
003-02	Mudded Fitting	Kitchen 2 nd Floor	NAD
003-03	Mudded Fitting Debris	Kitchen 2 nd Floor	NAD
	Ambient Sam	pling Event April 13, 2011	·
	Ambien	t Project# 110325AB	
01-01	Glazing	Exterior Door	Trace Chrysotile
01-02	Glazing	Exterior Door	Trace Chrysotile
02-01	02-01 Caulking Exterior Door		1.6% Tremolite
	0.4% C		0.4% Chrysotile
02-02			NA/PS
		npling Event June 3, 2011	
		t Project# 110601AA	1
•		Main Bldg. Vestibule – Center	NAD
004-02	Vapor Barrier	Main Bldg. Vestibule – Center	NAD
		pling Event June 16, 2011	
	Ambien	t Project# 110601AA	
006-01	Red Interior Window Caulk	2 nd Floor Main Vestibule	NAD
006-02	Red Interior Window Caulk	2 nd Floor Main Vestibule	NAD
007-01	Red Exterior Window Caulk	2 nd Floor Main Vestibule	NAD
007-02	Red Exterior Window Caulk	2 nd Floor Main Vestibule	NAD
008-01	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-02	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-03	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-04	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-05	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-06	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-07	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
009-01	Plaster Coat	Exterior Overhang	NAD
009-02	Plaster Coat	Exterior Overhang	NAD
009-03	Plaster Coat	Exterior Overhang	NAD
009-04	Plaster Coat	Exterior Overhang	NAD
009-05	Plaster Coat	Exterior Overhang	NAD
009-06	Plaster Coat	Exterior Overhang	NAD

Survey Date: Various

Page 1 of 10 SUNY Potsdam-Barrington Hall Student Union Updated: June 27, 2014

Sample Number	Type of Sample	Location of Sample	Asbestos Content	
009-07	Plaster Coat	Exterior Overhang	NAD	
	Ambient Sam	pling Event July 21, 2011		
	Ambient	Project# 110718AA		
01-01	Spray-On	East Entryway	NAD	
01-02	Spray-On	North Entryway	NAD	
01-03			NAD	
	Ambient Sampli	ing Event December 6, 2011		
	Ambient	Project# 111202AA		
		Bathrooms		
010-01	2x2 Ceramic Floor Tile	Room 121 Hall	NAD	
010-02	2x2 Ceramic Floor Tile	Room 120 Hall	NAD	
011-01	2x2 Ceramic Floor Tile Grout	Room 121 Hall	NAD	
011-02	2x2 Ceramic Floor Tile Grout	Room 120 Hall	NAD	
012-01	Brown Popcorn Ceiling	Room 120 Hall	NAD	
012-02	Brown Popcorn Ceiling	Room 207 Hall	NAD	
012-03	Brown Popcorn Ceiling	Room 121 Hall	NAD	
013-01	Brown 1x1 Ceramic Floor Tile	Room 122A Women	NAD	
013-02 Brown 1x1 Ceramic Floor Tile		Room 123A Men	NAD	
014-01	Brown 1x1 Floor Tile Grout	Room 122 Women	NAD	
014-02	Brown 1x1 Floor Tile Grout	Room 123A Men	NAD	
015-01	12x12 Terracotta Floor Tile	Room 207 Hall	NAD	
015-02	12x12 Terracotta Floor Tile	Room 206 Hall	NAD	
016-01	Yellow Floor Tile Mastic	Room 207 Hall	NAD	
016-02	Yellow Floor Tile Mastic	Room 206 Hall	NAD	
017-01	Yellow Carpet Mastic	Room 207 Hall	NAD	
017-02	Yellow Carpet Mastic	Room 207 Hall	NAD	
018-01	Black 6" Cove Base	Room 206 Hall	NAD	
018-02	Black 6" Cove Base	Room 207 Hall	NAD	
019-01	Yellow Cove Base Mastic	Room 206 Hall	NAD	
019-02	Yellow Cove Base Mastic	Room 207 Hall	NAD	
020-01	White 3x3 Ceramic Wall Tile	Room 125 Women	NAD	
020-02	White 3x3 Ceramic Wall Tile	Room 231 Women	NAD	
021-01	White 3x3 Ceramic Wall Tile Grout	Room 125 Women	NAD	

Page 2 of 10 SUNY Potsdam-Bo

Survey Date: Various

SUNY Potsdam-Barrington Hall Student Union Updated: June 27, 2014

Sample Number	Type of Sample	Location of Sample	Asbestos Content	
021-02	White 3x3 Ceramic Wall Tile Grout	Room 231 Women	NAD	
022-01	Plaster Wall Skim	Room 226 Women	NAD	
022-02	Plaster Wall Skim	Room 207 Hall	NAD	
022-03	Plaster Wall Skim	Room 121 Hall	NAD	
022-04	Plaster Wall Skim	Room 125 Women	NAD	
022-05	Plaster Wall Skim	1 11 12		
022-06	Plaster Wall Skim			
023-01	Plaster Wall Base	Room 226 Women	NAD	
023-02	Plaster Wall Base	Room 207 Hall	NAD	
023-03	Plaster Wall Base	Room 121 Hall	NAD	
023-04	Plaster Wall Base	Room 125 Women	NAD	
023-05	Plaster Wall Base	Room 123 Men	NAD	
024-01	Sheetrock	Room 120 Hall	NAD	
024-02	Sheetrock	Room 120 Hall	NAD	
025-01	Vinyl Wall Paper	Room 207 Hall	NAD	
025-02	Vinyl Wall Paper	Room 121 Hall	NAD	
026-01	Plaster Ceiling Skim	Room 231 Women	NAD	
026-02	Plaster Ceiling Skim	Room 124 Men	NAD	
026-03	Plaster Ceiling Skim	Room 123 Men	NAD	
027-01	Plaster Ceiling Base			
027-02	Plaster Ceiling Base	Room 124 Men	NAD	
027-03	Plaster Ceiling Base	Room 123 Men	NAD	
028-01	White Caulk	Room 231 Women Vanity	NAD	
028-02	White Caulk	Room 226 Women Vanity	NAD	
	Ambient Samp	pling Event March 1, 2012	•	
	Ambient	t Project# 120229AB		
2x4 Drop Ceiling Tile –		Room 219	NAD	
001-02	2x4 Drop Ceiling Tile – White w/ moderate horizontal fissures	Hall Adjacent to Mailroom	NAD	
002-01	2x4 Drop Ceiling Tile – White w/ large and deep horizontal fissures	College Store – Storage	NAD	

Survey Date: Various

Page 3 of 10 SUNY Potsdam-Barrington Hall Student Union Updated: June 27, 2014

Sample Number	Type of Sample	Location of Sample	Asbestos Content	
002-02	2x4 Drop Ceiling Tile – White w/ large and deep horizontal fissures	College Store – Storage	NAD	
003-01	1x1 Splined Ceiling Tile ⁽²⁾	Room 215	NAD	
003-02	1x1 Splined Ceiling Tile ⁽²⁾	Room 212	NAD	
	Ambient Sar	npling Event May 23, 2012	•	
	Ambien	t Project# 1200515AC		
029-01	Fitting Insulation	Large Diameter in Wet Wall	7.8% Chrysotile	
029-02	Fitting Insulation	Large Diameter in Wet Wall	NA/PS	
030-01	Fitting Insulation			
030-02	Fitting Insulation 1" Diameter in Wet Wall		NA/PS	
030-03	Fitting Insulation	nsulation 1" Diameter Debris in Wet Wall		
031-01			NAD	
031-02	Fitting Insulation	Above Ceiling @ Panel Access	NAD	
	Ambient Sar	npling Event July 10, 2012	•	
	Ambier	nt Project# 120709AB		
001-01	Ceiling Base	Exterior Overhang – Front Entrance	NAD	
001-02	Ceiling Base	Exterior Overhang – Front Entrance	NAD	
001-03	Ceiling Base	Exterior Overhang – Front Entrance	NAD	
002-01	Ceiling Finish	Exterior Overhang – Front Entrance	NAD	
002-02	Ceiling Finish	Exterior Overhang – Front Entrance	NAD	
002-03	Ceiling Finish	Exterior Overhang – Front Entrance	NAD	
003-01	Caulk	Inside/Outside Front Entrance Overhang	NAD	
003-02	Caulk	Inside/Outside Front Entrance Overhang	NAD	
	_	ling Event December 20, 2012 nt Project# 121221AG		
001-01	12x12 Orange VFT	2 nd Floor Bathroom	NAD	
001-01	12x12 Orange VFT	2 nd Floor Bathroom	NAD	
002-01	12x12 Grange VI I	2 nd Floor Bathroom	NAD	
002-01	12x12 Mastic	2 nd Floor Bathroom	NAD NAD	

Survey Date: Various

Sample Number	Type of Sample	Location of Sample	Asbestos Content
003-01	Debris on Floor	3 rd Floor Mechanical Room	NAD
003-02	Debris on Floor *	3 rd Floor Mechanical Room	30.8% Chrysotile
003-03	Debris on Floor *	3 rd Floor Mechanical Room	NA/PS
		ing Event February 26, 2013 Project #: 130222AA	
032-01	Debris- Mud Joint Packing	3 rd Floor Mechanical Room	NAD
032-02	Debris- Mud Joint Packing	g 3 rd Floor Mechanical Room NAD	
		pling Event March 7, 2013 Project #: 130307AA	
001-01	Cementious Debris	Kitchen Ramp	NAD
001-02	1		NAD
001-03	Cementious Board	Kitchen Ramp Door	NAD
002-01	Sheetrock	2 nd Floor MPR	NAD
002-02	Sheetrock	2 nd Floor MPR	
003-01	Joint Compound	2 nd Floor MPR	NAD
003-02	Joint Compound 2 nd Floor MPR		NAD
		pling Event March 21, 2013 t #: 130320AA- BASEMENT	
01-01	Insulation	Steam Line-Basement	12.5% Amosite Trace Chrysotile
01-02	Insulation	Steam Line-Basement	NA/PS
01-03	Insulation	Steam Line-Basement	NA/PS
02-01	Mudded Fitting	Non Leaking Pipe-Basement	NAD
02-02	Mudded Fitting	Non Leaking Pipe-Basement	NAD
02-03	Mudded Fitting	Non Leaking Pipe-Basement	NAD
03-01	Mudded Fitting	Leaking Pipe-Basement	NAD
03-02	Mudded Fitting	Leaking Pipe-Basement	NAD
03-03	Mudded Fitting	Leaking Pipe-Basement	NAD
04-01	Mudded Fitting	Chilled Water Supply Elbow	NAD
04.00			
04-02	Mudded Fitting	Chilled Water Supply Elbow	NAD
04-02	Mudded Fitting Mudded Fitting	Chilled Water Supply Elbow	NAD NAD
		== :	
04-03	Mudded Fitting	Chilled Water Supply Elbow	NAD
04-03 05-01	Mudded Fitting Mudded Fitting	Chilled Water Supply Elbow Chilled Water Return Elbow	NAD NAD

Survey Date: Various

Page 5 of 10 SUNY Potsdam-Barrington Hall Student Union Updated: June 27, 2014

Sample Number	Type of Sample	Location of Sample	Asbestos Content	
06-02	Mudded Fitting	Sewer Drain Cleanout	NA/PS	
06-03	Mudded Fitting	Sewer Drain Cleanout	NA/PS	
07-01	Debris # 2 *	Debris pile #2	25.0% Amosite	
07-02	Debris # 2 *	Debris pile #2	NA/PS	
08-01	Debris #3 *	Debris pile #3	NAD	
08-02	Debris #3 *	Debris pile #3	NAD	
09-01	Debris #1 *	Debris pile #1	30.8% Amosite	
09-02	Debris #1 *	Debris pile #1	NA/PS	
		pling Event March 26, 2013 t Project #: 130320AA		
01-01	Fire Doors	East Entry to Post Office	30.8% Amosite	
01-02	Fire Doors	East Entry to Post Office	26.7% Amosite	
01-03	Fire Doors	2 nd Floor Kitchen Doors	30.8% Amosite	
01-04	Fire Doors	2 nd Floor Kitchen Doors	23.5% Amosite	
01-05	Fire Doors	2 nd Floor Center Hallway	17.4% Amosite	
01-06	Fire Doors 2 nd Floor Center Hallway		17.4% Amosite	
02-07	7 Blue Grey Floor Tile 1 st Floor Dining Area		NAD	
02-08	Blue Grey Floor Tile	1 st Floor Dining Area	NAD	
02-09	Green Floor Tile	1 st Floor Dining Area	NAD	
02-10	Green Floor Tile	1 st Floor Dining Area	NAD	
02-11	Green and Red Floor Tile	1 st Floor Dining Area	NAD	
02-12	Green and Red Floor Tile	1 st Floor Dining Area	NAD	
02-13	Black Floor Tile	1 st Floor Dining Area	NAD	
02-14	Black Floor Tile	1 st Floor Dining Area	NAD	
03-15	Cove Base	1 st Floor Dining Area	NAD	
03-16	Cove Base	1 st Floor Dining Area	NAD	
03-17	Tile Adhesive	1 st Floor Dining Area	NAD	
03-18	Tile Adhesive	1 st Floor Dining Area	NAD	
		npling Event April 18, 2013 t Project #: 130419AC		
01-01	Skimcoat - Wall	Center Hallway of Petes Place-2 nd Floor	NAD	
01-02	Skimcoat - Wall	Contar Hallway of Potos Place 2nd		
01-03	Skimcoat - Wall	Center Hallway of Petes Place-2 nd Floor	NAD	

Page 6 of 10

Survey Date: Various

SUNY Potsdam-Barrington Hall Student Union Updated: June 27, 2014

Sample Number	Type of Sample	Location of Sample	Asbestos Content
01-04	Skimcoat - Wall	Center Hallway of Petes Place-2 nd Floor	NAD
01-05	Skimcoat - Wall	ncoat - Wall Center Hallway of Petes Place-2 nd Floor	
02-06	Plaster-Wall (Finish Coat) Center Hallway of Petes Place Floor		NAD
02-07	Plaster-Wall (Finish Coat)	Center Hallway of Petes Place-2 nd Floor	NAD
02-08	Plaster-Wall (Finish Coat)	Center Hallway of Petes Place-2 nd Floor	NAD
02-09	Plaster-Wall (Finish Coat)	Center Hallway of Petes Place-2 nd Floor	NAD
02-10	Plaster-Wall (Finish Coat)	Center Hallway of Petes Place-2 nd Floor	NAD
03-11	Wall Protector	Center Hallway of Petes Place-2 nd Floor	NAD
03-12	Wall Protector	Center Hallway of Petes Place-2 nd Floor	NAD
04-13	Floor - Tan Tile 12x12	oor - Tan Tile 12x12 East Lobby	
04-14	Floor - Tan Tile 12x12	West Lobby	NAD
05-15	Floor - White Tile 12x12	East Lobby	NAD
05-16	Floor - White Tile 12x12	East Lobby	NAD
06-17	Floor - Grey Tile 12x12	West Lobby	NAD
06-18	Floor - Grey Tile 12x12	West Lobby	NAD
07-19	Floor Tile Adhesive (all colors)	East Lobby	NAD
07-20	Floor Tile Adhesive (all colors)	West Lobby	NAD
08-21	Cove Base	East Lobby	NAD
08-22	Cove Base	West Lobby	NAD
09-23	Cove Base Glue	East Lobby	NAD
09-24	Cove Base Glue	West Lobby	NAD
		npling Event May 21, 2013 t Project #: 130520AA Dining Hall ⁽¹⁾	
01-01	Green Floor Tile	Outside West Entrance	NAD
02-02	Red Floor Tile	4' West of Counter	NAD

Survey Date: Various

Sample Number	Type of Sample	Location of Sample	Asbestos Content	
03-04	White 9x9 Floor Tile	4' from North below Stage	NAD	
03-03	White 9x9 Floor Tile	Center, below Stage	NAD	
04-05	Yellow (9x9) Tile Adhesive	West end of Stage	NAD	
04-06	Yellow (9x9) Tile Adhesive	6' from West end of Stage	NAD	
05-07	Debris	West side of counter	NAD	
05-08	Debris	West side of counter NAD		
	Ambient	pling Event May 29, 2013 Project #: 130520AA sement Area 2		
B501-01	Mudded Fitting	Roof Drain	0.97% Amosite	
B501-02	Mudded Fitting	Roof Drain	0.95% Amosite	
B501-03	Mudded Fitting	Roof Drain	0.98% Amosite	
B502-04	Mudded Fitting	Condensation Line	NAD	
0101 01	Baser	Project # 140107AA ment Mechanical	Taris	
0101-01	Mudded Fitting	Small Valve Mechanical Line 1	NAD	
	2	ng Event: January 15, 2014 nd Floor Hall		
0102-01	12x12 Crag Ceiling Tile ⁽²⁾	2 nd Floor Hall, by Room 217	NAD	
0102-02	12x12 Crag Ceiling Tile ⁽²⁾	2 nd Floor Hall, by Room 217	NAD	
		oling Event March 6, 2014 Project # 140307AA		
02D-01	Debris	Entry Hall, Above Ceiling	NAD	
02D-02	Debris	Storage By Entry Hall	NAD	
02D-03	Debris	Storage By Entry Hall	NAD	
02DE-04	Debris(Elbow)	Storage By Sales Floor	6.7% Chrysotile	
02DE-05	Debris(Elbow)	Storage By Sales Floor	NA/PS	
0201-06	Mudded Elbow	Above Dairy	NAD	
0201-07	Mudded Elbow	Above Novelty Food	NAD	
0201-08	Mudded Elbow	Above Entry Lighting	NAD	
0202-09	12x12 Beige Floor Tile	Store Back Entry	1.6% Chrysotile	
0202-10	12x12 Beige Floor Tile	Store Back Entry	NA/PS	
0203-11	12x12 Black Mastic	Store Back Entry	NAD	
0203-12	12x12 Black Mastic	Store Back Entry	NAD	
0204-13	12x12 Light Gray Floor Tile	Store Back Entry	NAD	

Survey Date: Various

Page 8 of 10 SUNY Potsdam-Barrington Hall Student Union Updated: June 27, 2014

Sample Number	Type of Sample	Location of Sample	Asbestos Content
0204-14	12x12 Light Gray Floor Tile	Store Back Entry	NAD
	Ambient Sam	pling Event: May 15, 2014	
	Ambient	Project #140517AA	
	Room	s 126, 127 & 130A	
051401-01	1x1 Gray Ceiling Tile ⁽²⁾	Room 127, North East	NAD
051401-02	1x1 Gray Ceiling Tile ⁽²⁾	Room 127, North East	NAD
051402-03	Debris	Room 127, North East	NAD
051402-04	Debris	Room 127, North East	NAD
051403-05	Mudded Fitting	Room 127, North East	NAD
951403-06 Mudded Fitting		Room 127, North East	NAD
051403-07 Mudded Fitting		Room 127, North East	NAD
051404-08 Duct Insulation		Room 130A, Center	NAD
051404-09 Duct Insulation		Room 130A, Center	NAD
051404-10 Duct Insulation		Room 130A, Center	NAD
051405-11 12x12 Dark Grey Floor Tile		Room 130A, At Door	NAD
051405-12	12x12 Dark Grey Floor Tile	Room 130A, Center	NAD
051406-13	12x12 Yellow Floor Tile	Room 130A, At Door	NAD
051406-14 12x12 Yellow Floor Tile		Room 130A, South End	NAD
051407-15	12x12 Black Floor Tile	Room 130A, North Side	NAD
051407-16	12x12 Black Floor Tile	Room 130A, North Side	NAD
051408-17	Black Floor Tile Mastic	Room 130A, North Side	NAD
051408-18	Black Floor Tile Mastic	Room 130A, North Side	NAD
051409-19	Fire Door Insulation	Room 130A, Door To Room 126A	33.3% Chrysoti
051409-20	Fire Door Insulation	Room 130A, Door To Room 126A	NA/PS
	Ambient Sam	pling Event: May 22, 2014	
	Ambient	Project #: 140522AC	
		Exterior	
0514101- 01	Brick	West Exterior , North End	NAD
0514101- 02	West Exterior, By North		NAD
0514102- 03			NAD
0514102- 04	Brick Grout	West Exterior, By North	NAD

SUNY Potsdam-Barrington Hall Student Union *Updated: June 27, 2014*

Sample Number	Type of Sample	Location of Sample	Asbestos Content	
Ambient Sampling Event: June 24, 2014 Ambient Project # 140613AD				
	Cookies	& Cream Rm 130A		
061410-01 Water Guard Under Tile		Room 130A, East Side	NAD	
061410-02	Water Guard Under Tile	Room 130A, East Side	NAD	
061411-03	Floor Leveler	Room 130A, West Side	NAD	
061411-04	Floor Leveler	Room 130A, West Side	NAD	
061412-05	Mudded Fitting	Room 130A, North West	26.7% Chrysotile	
061412-06	Mudded Fitting	Room 130A, North West	NA/PS	
061412-07	Mudded Fitting	Room 130A, North West	NA/PS	

NAD - No asbestos detected

NA/PS – Not analyzed, positive stop. First sample in homogenous grouping positive.

NA – Not analyzed

Survey Date: Various

- (1) The floor tile samples collected on this date were part of an assessment for a potential incidental disturbance. The white 9x9 floor tile and mastic was discovered under the green and red floor tile (non asbestos containing) during a renovation. The green and red floor tile sampled on this date were just confirmatory samples for those previously collected on March 26, 2013 and found to be negative for asbestos. All results indicate that there was no asbestos disturbance in this area.
- Ambient Environmental was directed to sample 1'x1' splined ceiling tiles in Barrington Student Union. We have determined that the 1x1 splined ceiling tiles sampled and present throughout Barrington Student Union are homogeneous to one another. The samples that were collected are representative of all 1x1 splined ceiling tiles within this building. Although there are different descriptions noted in this table for each 1x1 ceiling tile collected, a NYS licensed asbestos inspector surveyed the tiles in June 2014 and has determined they are homogeneous.

Page 10 of 10 SUNY Potsdam-Barrington Hall Student Union Updated: June 27, 2014

^{*} Samples collected as part of a contamination assessment to address an incidental disturbance in the basement. A site specific variance was developed and approved by NYSDOL. A contractor is scheduled to perform cleanup activities in April 2013.

SUNY POTSDAM BARRINGTON STUDENT UNION ASBESTOS CONTAINING MATERIALS

Sample No.	Material Description	Sample Location	Asbestos %	Homogenous Locations	Condition	Friability	Qty*
02-01	Caulking	Exterior Door	1.6% Tremolite 0.4% Chrysotile	TBD	Good	Friable	<10 sq ft
029-01	Fitting Insulation	Large Diameter in Wet Wall	7.8% Chrysotile	TBD	Good	Friable	<10 sq ft
030-01	Fitting Insulation	1" Diameter in Wet Wall	8.7% Chrysotile	TBD	Good	Friable	<10 sq ft
003-02	Debris on Floor	3 rd Floor Mechanical Room	30.8% Chrysotile	TBD	Damaged	Friable	<10 sq ft
01-01	Fire Doors	East Entry to Post Office	30.8% Amosite	TBD	Damaged	Friable	60 sq ft
01-02	Fire Doors	East Entry to Post Office	26.7% Amosite	TBD	Damaged	Friable	60 sq ft
01-03	Fire Doors	2 nd Floor Kitchen Doors	30.8% Amosite	TBD	Damaged	Friable	50 sq ft
01-04	Fire Doors	2 nd Floor Kitchen Doors	23.5% Amosite	TBD	Damaged	Friable	50 sq ft
01-05	Fire Doors	2 nd Floor Center Hallway	17.4% Amosite	TBD	Damaged	Friable	60 sq ft
01-06	Fire Doors	2 nd Floor Center Hallway	17.4% Amosite	TBD	Damaged	Friable	60 sq ft
01-01	Insulation	Steam Line-Basement	12.5% Amosite Trace Chrysotile	TBD	Significantly Damaged	Friable	
06-01	Mudded Fitting	Sewer Drain Cleanout	1.3% Amosite	TBD	Significantly Damaged	Friable	
07-01	Debris # 2 **	Debris pile #2	25.0% Amosite	TBD	Significantly Damaged	Friable	
09-01	Debris #1 **	Debris pile #1	30.8% Amosite	TBD	Significantly Damaged	Friable	
02DE-04	Debris (Elbow)	Storage By Sales Floor	6.7% Chrysotile	1 Elbow Above Ceiling Tile	Damaged	Friable	1 ln. ft.

Sample No.	Material Description	Sample Location	Asbestos %	Homogenous Locations	Condition	Friability	Qty*
0202-09	12x12 Beige Floor Tile	Store Back Entry	1.6% Chrysotile	Back Hallway of 2 nd Fl Hallway	Damaged	Non- Friable	60 sq. ft.
051409- 19	Fire Door Insulation	Room 130A, Door To Room 126A	33.3% Chrysotile				
061412- 05	Mudded Fitting	Room 130A, North West	26.7% Chrysotile				

^{*} Quantities are only estimates and should be field verified.

^{*} Quantities only reflect renovation areas and do not represent other homogeneous locations throughout the school.

^{**} Samples collected as part of a contamination assessment to address an incidental disturbance in the basement. A site specific variance was developed and approved by NYSDOL. A contractor is scheduled to perform cleanup activities in April 2013.