



Response Labs, LLC.
12 Colvin Avenue, Albany NY 12206
Phone (518) 482-5630 Fax (518) 482-5624
NYS DOH ELAP # 11917

PLM Bulk Asbestos Report

Client: SUNY Potsdam
44 Pierrepont Avenue
Potsdam NY 13676

Client Project Number: 29-020712

Project Name: Barrington Hall Entrance
44 Pierrepont Avenue
Sampling Area: Room 100A

Laboratory Job Number: 930-482
Sampled By: Client
Collection Date: 2/7/2012
Date Received: 2/14/2012

Lab Sample #	Customer Sample #	Homogeneity	Color	% Non-Fibrous Matrix Material	Gravimetric Test			Total % of Asbestos
					% of Organics	% of Acid Soluble Inorganics	% of Residue	
7250	I-1-BSU-100A	Homogeneous	White	100%				NAD
Sampled Material: Ceiling Plaster					Non-Asbestos Fibers	%	Asbestos Types:	
Sample Location: x=17.10 y=18.0 z=1.10					None Detected		No Asbestos Detected	
Analyzed By: Justin Adams Method: NYS ELAP 198.1								
Microscope: Olympus BH-2-214 Turn Around Time: 24 Hour					Analyzed Date: 2/14/2012			
7251	I-2-BSU-100A	Homogeneous	White	100%				NAD
Sampled Material: Ceiling Plaster					Non-Asbestos Fibers	%	Asbestos Types:	
Sample Location: x=17.10 y=18.0 z=1.10					None Detected		No Asbestos Detected	
Analyzed By: Justin Adams Method: NYS ELAP 198.1								
Microscope: Olympus BH-2-214 Turn Around Time: 24 Hour					Analyzed Date: 2/14/2012			
7252	I-3-BSU-100A	Homogeneous	White	100%				NAD
Sampled Material: Ceiling Plaster					Non-Asbestos Fibers	%	Asbestos Types:	
Sample Location: x=17.10 y=18.0 z=1.10					None Detected		No Asbestos Detected	
Analyzed By: Justin Adams Method: NYS ELAP 198.1								
Microscope: Olympus BH-2-214 Turn Around Time: 24 Hour					Analyzed Date: 2/14/2012			

Definitions of Abbreviations: **NOB:** Non-Organically Bound, **Trace:** Asbestos Detected at 1% or Less, **TEM:** Transmission Electron Microscope, **Inc.:** Inconclusive, **NAD:** No Asbestos Detected, **NA/PS:** Not Analyzed Positive Stop, **NA:** Not Analyzed

Disclaimer: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. No Asbestos Detected or Trace results by PLM 198.6 are considered inconclusive, TEM is currently the only method that can be used to determine if materials can be considered as non asbestos containing in NY State. This report cannot be reproduced except in full without the approval of Response Labs, LLC. This PLM report relates ONLY to the items tested. Liability is limited to the cost of analysis. ELAP PLM Method 198.1 for friable samples or 198.6 for NOB Samples.

Comments:

Laboratory Director,

Justin Adams