

SUNY POTSDAM
BARRINGTON STUDENT UNION
SUMMARY OF ASBESTOS SAMPLES AND ANALYSIS RESULTS

Sample Number	Type of Sample	Location of Sample	Asbestos Content
Ambient Sampling Event January 25, 2011			
Ambient Project# 101214AB			
003-01	Mudded Fitting	Kitchen 2 nd Floor	NAD
003-02	Mudded Fitting	Kitchen 2 nd Floor	NAD
003-03	Mudded Fitting Debris	Kitchen 2 nd Floor	NAD
Ambient Sampling Event April 13, 2011			
Ambient Project# 110325AB			
01-01	Glazing	Exterior Door	Trace Chrysotile
01-02	Glazing	Exterior Door	Trace Chrysotile
02-01	Caulking	Exterior Door	1.6% Tremolite 0.4% Chrysotile
02-02	Caulking	Exterior Door	NA/PS
Ambient Sampling Event June 3, 2011			
Ambient Project# 110601AA			
004-01	Vapor Barrier	Main Bldg. Vestibule – Center	NAD
004-02	Vapor Barrier	Main Bldg. Vestibule – Center	NAD
Ambient Sampling Event June 16, 2011			
Ambient Project# 110601AA			
006-01	Red Interior Window Caulk	2 nd Floor Main Vestibule	NAD
006-02	Red Interior Window Caulk	2 nd Floor Main Vestibule	NAD
007-01	Red Exterior Window Caulk	2 nd Floor Main Vestibule	NAD
007-02	Red Exterior Window Caulk	2 nd Floor Main Vestibule	NAD
008-01	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-02	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-03	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-04	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-05	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-06	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
008-07	Concrete Ceiling	2 nd Floor Exterior Overhang	NAD
009-01	Plaster Coat	Exterior Overhang	NAD
009-02	Plaster Coat	Exterior Overhang	NAD
009-03	Plaster Coat	Exterior Overhang	NAD
009-04	Plaster Coat	Exterior Overhang	NAD
009-05	Plaster Coat	Exterior Overhang	NAD
009-06	Plaster Coat	Exterior Overhang	NAD
009-07	Plaster Coat	Exterior Overhang	NAD

SUNY POTSDAM
BARRINGTON STUDENT UNION
SUMMARY OF ASBESTOS SAMPLES AND ANALYSIS RESULTS

Sample Number	Type of Sample	Location of Sample	Asbestos Content
Ambient Sampling Event July 21, 2011			
Ambient Project# 110718AA			
01-01	Spray-On	East Entryway	NAD
01-02	Spray-On	North Entryway	NAD
01-03	Spray-On	West Entryway	NAD
Ambient Sampling Event December 6, 2011			
Ambient Project# 111202AA			
Bathrooms			
010-01	2x2 Ceramic Floor Tile	Room 121 Hall	NAD
010-02	2x2 Ceramic Floor Tile	Room 120 Hall	NAD
011-01	2x2 Ceramic Floor Tile Grout	Room 121 Hall	NAD
011-02	2x2 Ceramic Floor Tile Grout	Room 120 Hall	NAD
012-01	Brown Popcorn Ceiling	Room 120 Hall	NAD
012-02	Brown Popcorn Ceiling	Room 207 Hall	NAD
012-03	Brown Popcorn Ceiling	Room 121 Hall	NAD
013-01	Brown 1x1 Ceramic Floor Tile	Room 122A Women	NAD
013-02	Brown 1x1 Ceramic Floor Tile	Room 123A Men	NAD
014-01	Brown 1x1 Floor Tile Grout	Room 122 Women	NAD
014-02	Brown 1x1 Floor Tile Grout	Room 123A Men	NAD
015-01	12x12 Terracotta Floor Tile	Room 207 Hall	NAD
015-02	12x12 Terracotta Floor Tile	Room 206 Hall	NAD
016-01	Yellow Floor Tile Mastic	Room 207 Hall	NAD
016-02	Yellow Floor Tile Mastic	Room 206 Hall	NAD
017-01	Yellow Carpet Mastic	Room 207 Hall	NAD
017-02	Yellow Carpet Mastic	Room 207 Hall	NAD
018-01	Black 6" Cove Base	Room 206 Hall	NAD
018-02	Black 6" Cove Base	Room 207 Hall	NAD
019-01	Yellow Cove Base Mastic	Room 206 Hall	NAD
019-02	Yellow Cove Base Mastic	Room 207 Hall	NAD
020-01	White 3x3 Ceramic Wall Tile	Room 125 Women	NAD
020-02	White 3x3 Ceramic Wall Tile	Room 231 Women	NAD
021-01	White 3x3 Ceramic Wall Tile Grout	Room 125 Women	NAD
021-02	White 3x3 Ceramic Wall Tile Grout	Room 231 Women	NAD

SUNY POTSDAM
BARRINGTON STUDENT UNION
SUMMARY OF ASBESTOS SAMPLES AND ANALYSIS RESULTS

Sample Number	Type of Sample	Location of Sample	Asbestos Content
022-01	Plaster Wall Skim	Room 226 Women	NAD
022-02	Plaster Wall Skim	Room 207 Hall	NAD
022-03	Plaster Wall Skim	Room 121 Hall	NAD
022-04	Plaster Wall Skim	Room 125 Women	NAD
022-05	Plaster Wall Skim	Room 123 Men	NA
022-06	Plaster Wall Skim	Room 123 Men	NAD
023-01	Plaster Wall Base	Room 226 Women	NAD
023-02	Plaster Wall Base	Room 207 Hall	NAD
023-03	Plaster Wall Base	Room 121 Hall	NAD
023-04	Plaster Wall Base	Room 125 Women	NAD
023-05	Plaster Wall Base	Room 123 Men	NAD
024-01	Sheetrock	Room 120 Hall	NAD
024-02	Sheetrock	Room 120 Hall	NAD
025-01	Vinyl Wall Paper	Room 207 Hall	NAD
025-02	Vinyl Wall Paper	Room 121 Hall	NAD
026-01	Plaster Ceiling Skim	Room 231 Women	NAD
026-02	Plaster Ceiling Skim	Room 124 Men	NAD
026-03	Plaster Ceiling Skim	Room 123 Men	NAD
027-01	Plaster Ceiling Base	Room 231 Women	NAD
027-02	Plaster Ceiling Base	Room 124 Men	NAD
027-03	Plaster Ceiling Base	Room 123 Men	NAD
028-01	White Caulk	Room 231 Women Vanity	NAD
028-02	White Caulk	Room 226 Women Vanity	NAD
Ambient Sampling Event March 1, 2012 Ambient Project# 120229AB			
001-01	2x4 Drop Ceiling Tile – White w/ moderate horizontal fissures	Room 219	NAD
001-02	2x4 Drop Ceiling Tile – White w/ moderate horizontal fissures	Hall Adjacent to Mailroom	NAD
002-01	2x4 Drop Ceiling Tile – White w/ large and deep horizontal fissures	College Store – Storage	NAD
002-02	2x4 Drop Ceiling Tile – White w/ large and deep horizontal fissures	College Store – Storage	NAD
003-01	1x1 Splined Ceiling Tile	Room 215	NAD

SUNY POTSDAM
BARRINGTON STUDENT UNION
SUMMARY OF ASBESTOS SAMPLES AND ANALYSIS RESULTS

Sample Number	Type of Sample	Location of Sample	Asbestos Content
003-02	1x1 Splined Ceiling Tile	Room 212	NAD
Ambient Sampling Event May 23, 2012 Ambient Project# 1200515AC			
029-01	Fitting Insulation	Large Diameter in Wet Wall	7.8% Chrysotile
029-02	Fitting Insulation	Large Diameter in Wet Wall	NA/PS
030-01	Fitting Insulation	1" Diameter in Wet Wall	8.7% Chrysotile
030-02	Fitting Insulation	1" Diameter in Wet Wall	NA/PS
030-03	Fitting Insulation	1" Diameter Debris in Wet Wall	NA/PS
031-01	Fitting Insulation	Above Ceiling @ Panel Access	NAD
031-02	Fitting Insulation	Above Ceiling @ Panel Access	NAD
Ambient Sampling Event July 10, 2012 Ambient Project# 120709AB			
001-01	Ceiling Base	Exterior Overhang – Front Entrance	NAD
001-02	Ceiling Base	Exterior Overhang – Front Entrance	NAD
001-03	Ceiling Base	Exterior Overhang – Front Entrance	NAD
002-01	Ceiling Finish	Exterior Overhang – Front Entrance	NAD
002-02	Ceiling Finish	Exterior Overhang – Front Entrance	NAD
002-03	Ceiling Finish	Exterior Overhang – Front Entrance	NAD
003-01	Caulk	Inside/Outside Front Entrance Overhang	NAD
003-02	Caulk	Inside/Outside Front Entrance Overhang	NAD
Ambient Sampling Event December 20, 2012 Ambient Project# 121221AG			
001-01	12x12 Orange VFT	2 nd Floor Bathroom	NAD
001-02	12x12 Orange VFT	2 nd Floor Bathroom	NAD
002-01	12x12 Mastic	2 nd Floor Bathroom	NAD
002-02	12x12 Mastic	2 nd Floor Bathroom	NAD
003-01	Debris on Floor	3 rd Floor Mechanical Room	NAD
003-02	Debris on Floor *	3 rd Floor Mechanical Room	30.8% Chrysotile
003-03	Debris on Floor *	3 rd Floor Mechanical Room	NA/PS

SUNY POTSDAM
BARRINGTON STUDENT UNION
SUMMARY OF ASBESTOS SAMPLES AND ANALYSIS RESULTS

Sample Number	Type of Sample	Location of Sample	Asbestos Content
Ambient Sampling Event February 26, 2013 Ambient Project #: 130222AA			
032-01	Debris- Mud Joint Packing	3 rd Floor Mechanical Room	NAD
032-02	Debris- Mud Joint Packing	3 rd Floor Mechanical Room	NAD
Ambient Sampling Event March 7, 2013 Ambient Project #: 130307AA			
001-01	Cementious Debris	Kitchen Ramp	NAD
001-02	Cementious Board	Kitchen Ramp Door	NAD
001-03	Cementious Board	Kitchen Ramp Door	NAD
002-01	Sheetrock	2 nd Floor MPR	NAD
002-02	Sheetrock	2 nd Floor MPR	NAD
003-01	Joint Compound	2 nd Floor MPR	NAD
003-02	Joint Compound	2 nd Floor MPR	NAD
Ambient Sampling Event March 21, 2013 Ambient Project #: 130320AA- BASEMENT			
01-01	Insulation	Steam Line-Basement	12.5% Amosite Trace Chrysotile
01-02	Insulation	Steam Line-Basement	NA/PS
01-03	Insulation	Steam Line-Basement	NA/PS
02-01	Mudded Fitting	Non Leaking Pipe-Basement	NAD
02-02	Mudded Fitting	Non Leaking Pipe-Basement	NAD
02-03	Mudded Fitting	Non Leaking Pipe-Basement	NAD
03-01	Mudded Fitting	Leaking Pipe-Basement	NAD
03-02	Mudded Fitting	Leaking Pipe-Basement	NAD
03-03	Mudded Fitting	Leaking Pipe-Basement	NAD
04-01	Mudded Fitting	Chilled Water Supply Elbow	NAD
04-02	Mudded Fitting	Chilled Water Supply Elbow	NAD
04-03	Mudded Fitting	Chilled Water Supply Elbow	NAD
05-01	Mudded Fitting	Chilled Water Return Elbow	NAD
05-02	Mudded Fitting	Chilled Water Return Elbow	NAD
05-03	Mudded Fitting	Chilled Water Return Elbow	NAD
06-01	Mudded Fitting	Sewer Drain Cleanout	1.3% Amosite
06-02	Mudded Fitting	Sewer Drain Cleanout	NA/PS
06-03	Mudded Fitting	Sewer Drain Cleanout	NA/PS
07-01	Debris # 2 *	Debris pile #2	25.0% Amosite
07-02	Debris # 2 *	Debris pile #2	NA/PS

SUNY POTSDAM
BARRINGTON STUDENT UNION
SUMMARY OF ASBESTOS SAMPLES AND ANALYSIS RESULTS

Sample Number	Type of Sample	Location of Sample	Asbestos Content
08-01	Debris #3 *	Debris pile #3	NAD
08-02	Debris #3 *	Debris pile #3	NAD
09-01	Debris #1 *	Debris pile #1	30.8% Amosite
09-02	Debris #1 *	Debris pile #1	NA/PS
Ambient Sampling Event March 26, 2013 Ambient Project #: 130320AA			
01-01	Fire Doors	East Entry to Post Office	30.8% Amosite
01-02	Fire Doors	East Entry to Post Office	26.7% Amosite
01-03	Fire Doors	2 nd Floor Kitchen Doors	30.8% Amosite
01-04	Fire Doors	2 nd Floor Kitchen Doors	23.5% Amosite
01-05	Fire Doors	2 nd Floor Center Hallway	17.4% Amosite
01-06	Fire Doors	2 nd Floor Center Hallway	17.4% Amosite
02-07	Blue Grey Floor Tile	1 st Floor Dining Area	NAD
02-08	Blue Grey Floor Tile	1 st Floor Dining Area	NAD
02-09	Green Floor Tile	1 st Floor Dining Area	NAD
02-10	Green Floor Tile	1 st Floor Dining Area	NAD
02-11	Green and Red Floor Tile	1 st Floor Dining Area	NAD
02-12	Green and Red Floor Tile	1 st Floor Dining Area	NAD
02-13	Black Floor Tile	1 st Floor Dining Area	NAD
02-14	Black Floor Tile	1 st Floor Dining Area	NAD
03-15	Cove Base	1 st Floor Dining Area	NAD
03-16	Cove Base	1 st Floor Dining Area	NAD
03-17	Tile Adhesive	1 st Floor Dining Area	NAD
03-18	Tile Adhesive	1 st Floor Dining Area	NAD
Ambient Sampling Event April 18, 2013 Ambient Project #: 130419AC			
01-01	Skimcoat - Wall	Center Hallway of Petes Place-2 nd Floor	NAD
01-02	Skimcoat - Wall	Center Hallway of Petes Place-2 nd Floor	NAD
01-03	Skimcoat - Wall	Center Hallway of Petes Place-2 nd Floor	NAD
01-04	Skimcoat - Wall	Center Hallway of Petes Place-2 nd Floor	NAD
01-05	Skimcoat - Wall	Center Hallway of Petes Place-2 nd Floor	NAD

SUNY POTSDAM
BARRINGTON STUDENT UNION
SUMMARY OF ASBESTOS SAMPLES AND ANALYSIS RESULTS

Sample Number	Type of Sample	Location of Sample	Asbestos Content
02-06	Plaster-Wall (Finish Coat)	Center Hallway of Petes Place-2 nd Floor	NAD
02-07	Plaster-Wall (Finish Coat)	Center Hallway of Petes Place-2 nd Floor	NAD
02-08	Plaster-Wall (Finish Coat)	Center Hallway of Petes Place-2 nd Floor	NAD
02-09	Plaster-Wall (Finish Coat)	Center Hallway of Petes Place-2 nd Floor	NAD
02-10	Plaster-Wall (Finish Coat)	Center Hallway of Petes Place-2 nd Floor	NAD
03-11	Wall Protector	Center Hallway of Petes Place-2 nd Floor	NAD
03-12	Wall Protector	Center Hallway of Petes Place-2 nd Floor	NAD
04-13	Floor - Tan Tile 12x12	East Lobby	NAD
04-14	Floor - Tan Tile 12x12	West Lobby	NAD
05-15	Floor - White Tile 12x12	East Lobby	NAD
05-16	Floor - White Tile 12x12	East Lobby	NAD
06-17	Floor - Grey Tile 12x12	West Lobby	NAD
06-18	Floor - Grey Tile 12x12	West Lobby	NAD
07-19	Floor Tile Adhesive (all colors)	East Lobby	NAD
07-20	Floor Tile Adhesive (all colors)	West Lobby	NAD
08-21	Cove Base	East Lobby	NAD
08-22	Cove Base	West Lobby	NAD
09-23	Cove Base Glue	East Lobby	NAD
09-24	Cove Base Glue	West Lobby	NAD

NAD – No asbestos detected

NA/PS – Not analyzed, positive stop. First sample in homogenous grouping positive.

NA – Not analyzed

* Samples collected as part of a contamination assessment to address an incidental disturbance in the basement. A site specific variance was developed and approved by NYSDOL. A contractor is scheduled to perform cleanup activities in April 2013.

**SUNY POTSDAM
BARRINGTON STUDENT UNION
ASBESTOS CONTAINING MATERIALS**

Sample No.	Material Description	Sample Location	Asbestos %	Homogenous Locations	Condition	Friability	Qty*
02-01	Caulking	Exterior Door	1.6% Tremolite 0.4% Chrysotile	TBD	Good	Friable	<10 sq ft
029-01	Fitting Insulation	Large Diameter in Wet Wall	7.8% Chrysotile	TBD	Good	Friable	<10 sq ft
030-01	Fitting Insulation	1" Diameter in Wet Wall	8.7% Chrysotile	TBD	Good	Friable	<10 sq ft
003-02	Debris on Floor	3 rd Floor Mechanical Room	30.8% Chrysotile	TBD	Damaged	Friable	<10 sq ft
01-01	Fire Doors	East Entry to Post Office	30.8% Amosite	TBD	Damaged	Friable	60 sq ft
01-02	Fire Doors	East Entry to Post Office	26.7% Amosite	TBD	Damaged	Friable	60 sq ft
01-03	Fire Doors	2 nd Floor Kitchen Doors	30.8% Amosite	TBD	Damaged	Friable	50 sq ft
01-04	Fire Doors	2 nd Floor Kitchen Doors	23.5% Amosite	TBD	Damaged	Friable	50 sq ft
01-05	Fire Doors	2 nd Floor Center Hallway	17.4% Amosite	TBD	Damaged	Friable	60 sq ft
01-06	Fire Doors	2 nd Floor Center Hallway	17.4% Amosite	TBD	Damaged	Friable	60 sq ft
01-01	Insulation	Steam Line-Basement	12.5% Amosite Trace Chrysotile	TBD	Significantly Damaged	Friable	
06-01	Mudded Fitting	Sewer Drain Cleanout	1.3% Amosite	TBD	Significantly Damaged	Friable	
07-01	Debris # 2 **	Debris pile #2	25.0% Amosite	TBD	Significantly Damaged	Friable	
09-01	Debris #1 **	Debris pile #1	30.8% Amosite	TBD	Significantly Damaged	Friable	

* Quantities are only estimates and should be field verified.

* Quantities only reflect renovation areas and do not represent other homogeneous locations throughout the school.

** Samples collected as part of a contamination assessment to address an incidental disturbance in the basement. A site specific variance was developed and approved by NYSDOL. A contractor is scheduled to perform cleanup activities in April 2013.

**AmeriSci New York**

117 EAST 30TH ST.

NEW YORK, NY 10018

TEL: (212) 679-8800 • FAX: (212) 679-3114

PLM Bulk Asbestos Report

Ambient Environmental, Inc.

Attn: Joella Viscusi

12 Colvin Avenue

Albany, NY 12206

Date Received 04/20/13

Date Examined 04/20/13

ELAP # 11480

RE: 130419AC; SUNY Potsdam; Barrington Hall - Inspection; Rt.

56, Potsdam, NY; Main Lobby & 2nd Floor Pete's Place

AmeriSci Job # 213043980

P.O. #

Page 1 of 5

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
01	213043980-01	No	NAD
01	Location: Skim Coat, Center Of Hallway Of Pete's Pl.		(by NYS ELAP 198.1) by Karol H. Lu on 04/20/13
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Non-fibrous 100 %			
02	213043980-02	No	NAD
01	Location: Skim Coat, Center Hallways Of Pete's Pl.		(by NYS ELAP 198.1) by Karol H. Lu on 04/20/13
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Non-fibrous 100 %			
03	213043980-03	No	NAD
01	Location: Skim Coat, Center Hallways Of Petes Pl.		(by NYS ELAP 198.1) by Karol H. Lu on 04/20/13
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Non-fibrous 100 %			
04	213043980-04	No	NAD
01	Location: Skim Coat, Center Hallways Of Petes Pl.		(by NYS ELAP 198.1) by Karol H. Lu on 04/20/13
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Non-fibrous 100 %			
05	213043980-05	No	NAD
01	Location: Skim Coat, Center Hallways Of Petes Pl.		(by NYS ELAP 198.1) by Karol H. Lu on 04/20/13
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Non-fibrous 100 %			

AmeriSci Job #: 213043980

Client Name: Ambient Environmental, Inc.

Page 2 of 5

PLM Bulk Asbestos Report130419AC; SUNY Potsdam; Barrington Hall - Inspection; Rt.
56, Potsdam, NY; Main Lobby & 2nd Floor Pete's Place

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
06 02	213043980-06 Location: Plaster, Center Hallways Of Petes Pl.	No	NAD (by NYS ELAP 198.1) by Karol H. Lu on 04/20/13
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 %			
07 02	213043980-07 Location: Plaster, Center Hallways Of Petes Pl.	No	NAD (by NYS ELAP 198.1) by Karol H. Lu on 04/20/13
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 %			
08 02	213043980-08 Location: Plaster, Center Hallways Of Petes Pl.	No	NAD (by NYS ELAP 198.1) by Karol H. Lu on 04/20/13
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 %			
09 02	213043980-09 Location: Plaster, Center Hallways Of Petes Pl.	No	NAD (by NYS ELAP 198.1) by Karol H. Lu on 04/20/13
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 %			
10 02	213043980-10 Location: Plaster, Center Hallways Of Petes Pl.	No	NAD (by NYS ELAP 198.1) by Karol H. Lu on 04/20/13
Analyst Description: Grey, Homogeneous, Non-Fibrous, Cementitious, Bulk Material Asbestos Types: Other Material: Non-fibrous 100 %			
11 03	213043980-11 Location: Wall Protector, Center Hallways Of Pete's Pl.	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 5.7 %			

See Reporting notes on last page

AmeriSci Job #: 213043980

Client Name: Ambient Environmental, Inc.

Page 3 of 5

PLM Bulk Asbestos Report

130419AC; SUNY Potsdam; Barrington Hall - Inspection; Rt.
56, Potsdam, NY; Main Lobby & 2nd Floor Pete's Place

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
12 03	213043980-12 Location: Wall Protector, Center Hallways Of Pete's Pl.	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 7.8 %			
13 04	213043980-13 Location: Tan Tile 12x12, East Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: Light Brown, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 42.2 %			
14 04	213043980-14 Location: Tan Tile 12x12, West Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: Light Brown, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 43.5 %			
15 05	213043980-15 Location: White Tile 12x12, East Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 46.2 %			
16 05	213043980-16 Location: White Tile 12x12, East Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: White, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 43.6 %			
17 06	213043980-17 Location: Grey 12x12, West Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: Brown, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 9.3 %			

See Reporting notes on last page

AmeriSci Job #: 213043980

Client Name: Ambient Environmental, Inc.

Page 4 of 5

PLM Bulk Asbestos Report130419AC; SUNY Potsdam; Barrington Hall - Inspection; Rt.
56, Potsdam, NY; Main Lobby & 2nd Floor Pete's Place

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
18 06	213043980-18 Location: Grey 12x12, West Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: Brown, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 9.9 %			
19 07	213043980-19 Location: Tile Adhesive, East Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: Tan, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 3.6 %			
20 07	213043980-20 Location: Tile Adhesive, West Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: Tan, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 13 %			
21 08	213043980-21 Location: Cove Base, East Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: Black, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 1.6 %			
22 08	213043980-22 Location: Cove Base, West Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: Black, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 1.8 %			
23 09	213043980-23 Location: Cove Base Glue, East Lobby	No	NAD (by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: Tan, Homogeneous, Non-Fibrous, Bulk Material Asbestos Types: Other Material: Non-fibrous 26.3 %			

See Reporting notes on last page

AmeriSci Job #: 213043980

Client Name: Ambient Environmental, Inc.

Page 5 of 5

PLM Bulk Asbestos Report130419AC; SUNY Potsdam; Barrington Hall - Inspection; Rt.
56, Potsdam, NY; Main Lobby & 2nd Floor Pete's Place

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
24	213043980-24	No	NAD
09	Location: Cove Base Glue, West Lobby		(by NYS ELAP 198.6) by Karol H. Lu on 04/20/13
Analyst Description: Tan, Homogeneous, Non-Fibrous, Bulk Material			
Asbestos Types:			
Other Material: Non-fibrous 26.5 %			

Reporting Notes:Analyzed by: Karol H. Lu 

*NAD/NSD =no asbestos detected; NA =not analyzed; NA/PS=not analyzed/positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab Code 200546-0), ELAP PLM Method 198.1 for NY friable samples, which includes the identification and quantitation of vermiculite or 198.6 for NOB samples (NY ELAP Lab ID11480); Note:PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non asbestos-containing in NY State (also see EPA Advisory for floor tile, FR 59,146,38970,8/1/94) National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the lab.This PLM report relates ONLY to the items tested. AIHA Lab # 102843, RI Cert#AAL-094, CT Cert#PH-0186, Mass Cert#AA000054.

Reviewed By: _____

END OF REPORT _____

Table 1

Summary of Bulk Asbestos Analysis Results

130419AC; SUNY Potsdam; Barrington Hall-Inspection; Rt. 56, Potsdam, NY; Main Lobby & 2nd Floor Pete's Place

AmeriSci Sample #	Client Sample#	HG Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
01	01	01	---	---	---	---	NAD	NA
Location:	Skim Coat, Center Of Hallway Of Pete's Pl.							
02	02	01	---	---	---	---	NAD	NA
Location:	Skim Coat, Center Hallways Of Pete's Pl.							
03	03	01	---	---	---	---	NAD	NA
Location:	Skim Coat, Center Hallways Of Pete's Pl.							
04	04	01	---	---	---	---	NAD	NA
Location:	Skim Coat, Center Hallways Of Pete's Pl.							
05	05	01	---	---	---	---	NAD	NA
Location:	Skim Coat, Center Hallways Of Pete's Pl.							
06	06	02	---	---	---	---	NAD	NA
Location:	Plaster, Center Hallways Of Pete's Pl.							
07	07	02	---	---	---	---	NAD	NA
Location:	Plaster, Center Hallways Of Pete's Pl.							
08	08	02	---	---	---	---	NAD	NA
Location:	Plaster, Center Hallways Of Pete's Pl.							
09	09	02	---	---	---	---	NAD	NA
Location:	Plaster, Center Hallways Of Pete's Pl.							
10	10	02	---	---	---	---	NAD	NA
Location:	Plaster, Center Hallways Of Pete's Pl.							
11	11	03	0.123	76.4	17.9	5.7	NAD	NAD
Location:	Wall Protector, Center Hallways Of Pete's Pl.							
12	12	03	0.115	78.1	13.0	7.9	NAD	NAD
Location:	Wall Protector, Center Hallways Of Pete's Pl.							
13	13	04	0.199	26.1	31.7	42.2	NAD	NAD
Location:	Tan Tile 12x12, East Lobby							
14	14	04	0.313	23.6	32.9	43.5	NAD	NAD
Location:	Tan Tile 12x12, West Lobby							
15	15	05	0.210	26.2	27.6	46.2	NAD	NAD
Location:	White Tile 12x12, East Lobby							
16	16	05	0.156	27.6	28.8	43.6	NAD	NAD
Location:	White Tile 12x12, East Lobby							

See Reporting notes on last page

Table I

Summary of Bulk Asbestos Analysis Results

130419AC; SUNY Potsdam; Barrington Hall-Inspection; Rt. 56, Potsdam, NY; Main Lobby & 2nd Floor Pete's Place

AmeriSci Sample #	Client Sample#	HQ Area	Sample Weight (gram)	Heat Sensitive Organic %	Acid Soluble Inorganic %	Insoluble Non-Asbestos Inorganic %	** Asbestos % by PLM/DS	** Asbestos % by TEM
17	17	06	0.150	28.0	62.7	9.3	NAD	NAD
Location:	Grey 12x12, West Lobby							
18	18	06	0.232	23.7	66.4	9.9	NAD	NAD
Location:	Grey 12x12, West Lobby							
19	19	07	0.139	95.0	1.4	3.6	NAD	NAD
Location:	Tile Adhesive, East Lobby							
20	20	07	0.154	83.8	3.2	13.0	NAD	NAD
Location:	Tile Adhesive, West Lobby							
21	21	08	0.128	60.2	38.3	1.6	NAD	NAD
Location:	Cove Base, East Lobby							
22	22	08	0.110	60.0	38.2	1.8	NAD	NAD
Location:	Cove Base, West Lobby							
23	23	09	0.232	66.4	7.3	26.3	NAD	NAD
Location:	Cove Base Glue, East Lobby							
24	24	09	0.230	66.5	7.0	26.5	NAD	NAD
Location:	Cove Base Glue, West Lobby							

Analyzed by: Ravi N. Krishnapa *Ravi N. Krishnapa*; Date Analyzed 4/20/2013

**Quantitative Analysis (Semi/Full): Bulk Asbestos Analysis - PLM by EPA 600/M4-82-020 per 40 CFR or ELAP 198.1 for New York friable samples or ELAP 198.6 for New York NOB samples; TEM (Semi/Full) by EPA 600/R-83/116 (not covered by NVLAP Bulk accreditation) or ELAP 198.4; for New York samples; NAD = no asbestos detected during a quantitative analysis; NA = not analyzed; Trace = <1%; Quantification for beginning weights of <0.1 grams should be considered as qualitative only; Qualitative Analysis: Asbestos analysis results of "Present" or "NVA = No Visible Asbestos" represents results for Qualitative PLM or TEM Analysis only (no accreditation coverage available from any regulatory agency for qualitative analyses); AIHA Lab # 102843, NVLAP Lab Code 200546-0, NYSDOH ELAP Lab ID#11480.

Warning Note: PLM limitation, only TEM will resolve fibers <0.25 micrometers in diameter. TEM bulk analysis is representative of the fine grained matrix material and may not be representative of non-uniformly dispersed debris for which PLM evaluation is recommended (i.e. soils and other heterogeneous materials).

Reviewed By: _____

BULK SAMPLE DATA AND
CHAIN OF CUSTODY FORM

213043980

PROJECT INFORMATION

1. Client: SUNY Potsdam	2. Project Name: Barrington Hall - Inspection	2a. Project Street Address: Rt. 56 Potsdam, N.Y.	2b. Client Contact: Larry Leashomb
3. Project Number: 130419 AC	4. Inspector: Eric K. Roth	5. Collection Date: 4-18-13	
6. Sample TAT: ☐ 24 HR ☐ 48 HR ☐ 72 HR ☐ 5 Day ☒ Other RU3H	7. Building Name: Barrington Hall	8. Sampling Areas: Main lobby + 2nd Floor Petes Place	9. Comments: (Field) ☐ Analyze to First Positive By Homogeneous Material ☒ For Negative NOB PLM's, continue to TEM

BULK SAMPLE LOCATION

TYPE OF MATERIALS

10. Homogeneous Area Number	11. Bulk Sample ID Number	12. Sampled Material	13. Type of Material			14. Sample Location		15. Friability (N/F)	16. Condition (G, D, SD)	17. Quantity (LF, SF, EA)	18. Asbestos Content (Type & %)
			Surf	TSI	MISC	Sample Coordinates	Sample Coordinates				
01	01	Skimcoat	/			Center Hallways of Petes Pl.		F	D		
01	02	Skimcoat	/			Center Hallways of Petes Pl.		F	D		
01	03	Skimcoat	/			Center Hallways of Petes Pl.		F	D		
01	04	Skimcoat	/			Center Hallways of Petes Pl.		F	D		
01	05	Skim Coat	/			Center Hallways of Petes Pl.		F	D		
02	06	Plaster	/			Center Hallways of Petes Pl.		F	D		
02	07	Plaster	/			Center Hallways of Petes Pl.		F	D		
02	08	Plaster	/			Center Hallways of Petes Pl.		F	D		
02	09	Plaster	/			Center Hallways of Petes Pl.		F	D		
02	10	Plaster	/			Center Hallways of Petes Pl.		F	D		
03	11	Wall protector	/			Center Hallways of Petes Pl.		N/F	D		
03	12	Wall protector	/			Center Hallways of Petes Pl.		N/F	D		

CHAIN OF CUSTODY

19. Relinquished By: Eric K. Roth	20. Date	21. Time	22. Received By: Approved	23. Date 4/18/13	24. Time 1:55
II					
III					

LAB INFORMATION

25. Lab Name	26. Date	27. Time
a. Analyzed By: Kapov LV	4/18/13	1632
b. QC by:		
c. Lab Batch #:		

28. Ambient Project Manager: Joella Viscusi	29. Results To: Phone #/e: Fax:	30. Drawings: ☒ Sample Locations ☐ Material Locations	31. Comments:
---	---------------------------------------	--	---------------



Ambient Environmental, Inc.
Comprehensive Building Science Solutions
12 Corbin Ave. Albany, NY 12206
PH: 518-482-0704 / FX: 518-482-0750

NTS/NUS Certified PBE
& SBA ED/PBSB

Page 2 of 2

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

213043980

PROJECT INFORMATION

1. Client: SUNY Potsdam		2. Project Name: Barrington Hall - Inspection		2b. Client Contact: Larry Leeshomb	
3. Project Number: 130419AC		2a. Task Number: Inspection		6. Collection Date: 4-18-13	
6. Sample TAT: ☐ 24 HR ☐ 48 HR ☐ 72 HR ☐ 5 Day ☒ Other RUSH		7. Building Name: Barrington Hall		9. Comments: (Field) ☐ Analyze to First Positive By Homogeneous Material ☒ For Negative NOB PLUS, continue to TBM	
8. Sampling Area: Main lobby		10. Inspection: Erik K. Rath			

BULK SAMPLE LOCATION

TYPE OF MATERIALS

10. Laboratory Sample Number	11. Homogeneous Area Number	12. Bulk Sample Number	13. Sampled Material	14. Type of Material		15. Sample Location		16. Friability (NUF)	17. Condition (G, D, SD)	18. Quantity (LF, SF, EA)	19. Asbestos Content (Type & %)
				Surf	TSI	MISC	Sample Coordinates				
04	04	13	Tan Tile 12x12				East lobby	N	G	300 sq ft	
04	04	14	Tan Tile 12x12				West lobby	N	G	300 sq ft	
05	05	15	White Tile 12x12				East lobby	N	G	20 sq ft	
05	05	16	White Tile 12x12				East lobby	N	G	20 sq ft	
06	06	17	Grey 12x12				West lobby	N	G	20 sq ft	
06	06	18	Grey 12x12				West lobby	N	G	20 sq ft	
07	07	19	Tile Adhesive				East lobby	N	G	20 sq ft	
07	07	20	Tile Adhesive				West lobby	N	G	350 sq ft	
08	08	21	Cove base				East lobby	N	G	350 sq ft	
08	08	22	Cove base				West lobby	N	G	30' LF	
09	09	23	Cove base glue				East lobby	N	G	30' LF	
09	09	24	Cove base glue				West lobby	N	G	30' LF	

CHAIN OF CUSTODY

20. Requested By: Erik K. Rath	21. Date: 4-19-13	22. Time:	23. Received By: [Signature]	24. Date: 4/19/13	25. Time: 11:53
26. Ambient Project Manager: Joella Viscusi					

LAB INFORMATION

28. Lab Name	27. Date	28. Time
a. Analyzed By: KAPAL LV	04/20/13	16:22
b. QC by:		
c. Lab Batch #:		

31. Drawings: ☒ Sample Locations ☐ Material Locations	32. Comments:
---	---------------