



Response Labs, LLC
12 Colvin Avenue, Albany NY 12206
Phone (518) 482-5630 Fax (518) 482-5624
NYS DOH ELAP # 11917

PLM Bulk Asbestos Report

Client: Ambient Environmental Inc.
12 Colvin Avenue
Albany NY 12206

Client Project Number: 130529AA

Project Name: SUNY Potsdam
44 Pierrepont Avenue, Potsdam NY

Laboratory Batch Number: 1460-978

Sampling Area: Barrington Student Center-Basement Area 2

Sampled By: David Foote

Collection Date: 5/29/2013

Date Received: 5/30/2013

Lab Sample #	Customer Sample #	Homogeneity	Color	% Non-Fibrous Matrix Material	Gravimetric Test			Total % of Asbestos
					% of Organics	% of Acid Soluble Inorganics	% of Residue	
14518	B501-01	Homogeneous	Grey	66.3%				0.97%
Sampled Material: Muddled Fitting					Other Materials	%	Asbestos Types:	
Sample Location: Roof Drain					32.7% Fiber Glass	0.97%	Amosite	
Analyzed By: Justin Adams Method: NYS ELAP 198.1 (Friable)					Date: 5/30/2013			
Microscope: Olympus BH-2-214 Turn Around Time: 24 Hour								
14519	B501-02	Homogeneous	Grey	59.8%				0.95%
Sampled Material: Muddled Fitting					Other Materials	%	Asbestos Types:	
Sample Location: Roof Drain					39.2% Fiber Glass	0.95%	Amosite	
Analyzed By: Justin Adams Method: NYS ELAP 198.1 (Friable)					Date: 5/30/2013			
Microscope: Olympus BH-2-214 Turn Around Time: 24 Hour								
14520	B501-03	Homogeneous	Grey	65.8%				0.98%
Sampled Material: Muddled Fitting					Other Materials	%	Asbestos Types:	
Sample Location: Roof Drain					33.2% Fiber Glass	0.98%	Amosite	
Analyzed By: Justin Adams Method: NYS ELAP 198.1 (Friable)					Date: 5/30/2013			
Microscope: Olympus BH-2-214 Turn Around Time: 24 Hour								
14521	B502-04	Homogeneous	Grey	50%				NAD
Sampled Material: Muddled Fitting					Other Materials	%	Asbestos Types:	
Sample Location: Condensate Line					50% Fiber Glass		No Asbestos Detected	
Analyzed By: Justin Adams Method: NYS ELAP 198.1 (Friable)					Date: 5/30/2013			
Microscope: Olympus BH-2-214 Turn Around Time: 24 Hour								

Definitions of Abbreviations: NOB: Non-Organically Bound, Trace: Asbestos Detected at 1% or Less, TEM: Transmission Electron Microscope, Inc.: Inconclusive, NAD: No Asbestos Detected, NA/PS: Not Analyzed Positive Stop, NA: Not Analyzed, ACM: Asbestos Containing Material, NVA: No Visible Asbestos

Disclaimer: PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. No Asbestos Detected or Trace results by PLM 198.6 are considered inconclusive. TEM is currently the only method that can be used to determine if materials can be considered as non asbestos containing in NY State. This report cannot be reproduced except in full without the approval of Response Labs, LLC. This PLM report relates ONLY to the items tested. Liability is limited to the cost of analysis. ELAP PLM Method 198.1 for friable samples or 198.6 for NOB Samples. There is no accreditation coverage available from any regulatory agency for Qualitative PLM.

Laboratory Director,

Comments:

Justin Adams



12 Colvin Ave. Albany, NY 12208
PH: 518-482-0704 | FX: 518-482-0750

BULK SAMPLE DATA AND CHAIN OF CUSTODY FORM

PROJECT INFORMATION

1. Client:	SLURR Potbom		2. Project Name:	Misc. Bulk Sampling	2a. Project Address:	44 Riverport Ave	2b. Client Contact:	Leah Leashomb
3. Project Number:	130529 AA	3a. Task Number:		4. Inspector:	David Gorte	5. Collection Date:	5-29-13	
6. Sample TAT:	☒ 24 HR ☐ 48 HR ☐ 72 HR ☐ 5 Day ☐ Other		7. Building Name:	Barrington Student Center		8. Sampling Area:	Eastmost Area 2	
			9. Comments: (Field)	☒ Analyze to First Positive By Homogeneous Material ☐ For Negative NOB PLM's, continue to TEM				

BULK SAMPLE LOCATION

[illegible]

CHAIN OF CUSTODY

20. Requisitioned By:	21. Date	22. Time	23. Received By:	24. Date	25. Time
I. David Booth	5-20-15	10:00		5/30/15	1134
II					
III					

LAB INFORMATION

26. Lab Name	16310556	27. Date	1/4/17	28. Time	
a. Analyzed By:	1				
b. QC By:					
c. Lab Batch #:	1460-978				

29. Ambient Project Manager: <i>Isella Viscusi</i>	30. Results To: <i>Asbury</i> Phone #: _____ Fax: _____	31. Drawings: ☒ Sample Locations ☐ Material Locations	32. Comments:
---	---	---	---------------