



Please Reply To:

**AmeriSci New York**

117 EAST 30TH ST.  
NEW YORK, NY 10016  
TEL: (212) 679-8600 • FAX: (212) 679-3114

**FACSIMILE TELECOPY TRANSMISSION**

**To:** Joella Viscusi  
Ambient Environmental, Inc.  
**Fax #:** (518) 482-0750

**Email:** joellav@ambient-env.com, results@ambient-env.com

**From:** Karol H. Lu  
**AmeriSci Job #:** 215074067  
**Subject:** ELAP-PLM-FRIABLE rush Results  
**Client Project:** 150716AA; SUNY Potsdam;  
Barrington Student Union, 44  
Pierrepont Ave., Barringt

**Date:** Saturday, July 18, 2015

**Time:** 11:41:29

**Comments:**

**Number of Pages:**

3  
(including cover sheet)

CONFIDENTIALITY NOTICE: Unless otherwise indicated, the information contained in this communication is confidential information intended for use of the individual named above. If the reader of this communication is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is prohibited. If you have received this communication in error, please immediately notify the sender by telephone and return the original message to the above address via the US Postal Service at our expense. Preliminary data reported here will be verified before final report is issued. Samples are disposed of in 60 days or unless otherwise instructed by the protocol or special instructions in writing. Thank you.

**Certified Analysis    Service 24 Hours A Day • 7 Days A Week    Competitive Prices**  
visit our web site - [www.amerisci.com](http://www.amerisci.com)

**Boston • Los Angeles • New York • Richmond**

**AmeriSci New York**


117 EAST 30TH ST.  
NEW YORK, NY 10016  
TEL: (212) 679-8600 • FAX: (212) 679-3114

## PLM Bulk Asbestos Report

Ambient Environmental, Inc.  
Attn: Joella Viscusi  
12 Colvin Avenue  
  
Albany, NY 12206

**Date Received** 07/18/15    **AmeriSci Job #** 215074067  
**Date Examined** 07/18/15    **P.O. #**  
**ELAP #** 11480    **Page** 1 of 1  
**RE:** 150716AA; SUNY Potsdam; Barrington Student Union, 44  
Pierrepont Ave., Barrington Student Union, Kitchen Slop Sink  
Rm.

| Client No. / HGA                                                                                                                                                                | Lab No.      | Asbestos Present | Total % Asbestos                                                   |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|------------------|--------------------------------------------------------------------|
| 001<br>01 <b>Location:</b> Slop Sink Rm. - Mudded Elbow                                                                                                                         | 215074067-01 | <b>No</b>        | <b>NAD</b><br>(by NYS ELAP 198.1)<br>by Karol H. Lu<br>on 07/18/15 |
| <b>Analyst Description:</b> Grey, Homogeneous, Fibrous, Bulk Material<br><b>Asbestos Types:</b><br><b>Other Material:</b> Cellulose Trace, Fibrous glass 10 %, Non-fibrous 90 % |              |                  |                                                                    |
| 002<br>01 <b>Location:</b> Slop Sink Rm. - Mudded Valve                                                                                                                         | 215074067-02 | <b>No</b>        | <b>NAD</b><br>(by NYS ELAP 198.1)<br>by Karol H. Lu<br>on 07/18/15 |
| <b>Analyst Description:</b> Grey, Homogeneous, Fibrous, Bulk Material<br><b>Asbestos Types:</b><br><b>Other Material:</b> Cellulose Trace, Fibrous glass 10 %, Non-fibrous 90 % |              |                  |                                                                    |
| 003<br>01 <b>Location:</b> Outside Wall of Slop Sink Rm. - Mudded Elbow                                                                                                         | 215074067-03 | <b>No</b>        | <b>NAD</b><br>(by NYS ELAP 198.1)<br>by Karol H. Lu<br>on 07/18/15 |
| <b>Analyst Description:</b> Grey, Homogeneous, Fibrous, Bulk Material<br><b>Asbestos Types:</b><br><b>Other Material:</b> Cellulose 5 %, Fibrous glass 10 %, Non-fibrous 85 %   |              |                  |                                                                    |

**Reporting Notes:**Analyzed by: Karol H. Lu 

\*NAD/NSD =no asbestos detected; NA =not analyzed; NA/PS=not analyzed/positive stop; PLM Bulk Asbestos Analysis by EPA 600/M4-82-020 per 40 CFR 763 (NVLAP 200546-0), ELAP PLM Method 198.1 for NY friable samples, which includes the identification and quantitation of vermiculite or 198.6 for NOB samples or EPA 400 pt ct by EPA 600/M4-82-020 (NY ELAP Lab 11480); Note:PLM is not consistently reliable in detecting asbestos in floor coverings and similar non-friable organically bound materials. NAD or Trace results by PLM are inconclusive, TEM is currently the only method that can be used to determine if this material can be considered or treated as non asbestos-containing in NY State (also see EPA Advisory for floor tile, FR 59,146,38970,8/1/94) National Institute of Standards and Technology Accreditation requirements mandate that this report must not be reproduced except in full without the approval of the lab. This PLM report relates ONLY to the items tested. AIHA Lab 102843, RI Cert AAL-094, CT Cert PH-0186, Mass Cert AA000054.

Reviewed By: \_\_\_\_\_ END OF REPORT \_\_\_\_\_



|                                                                                                                                                                                                    |                                               |                                             |                                                                                                                                                                                   |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------|---------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1. Client:<br>Suby Potsebam                                                                                                                                                                        | 2. Project Name:<br>Barrington Student Union  | 2a. Project Address:<br>44 Pierrepont Ave   | 2b. Client Contact:<br>Larry Leashomb                                                                                                                                             |
| 3. Project Number:<br>150716 AA                                                                                                                                                                    | 3a. Task Number:                              | 4. Inspector:<br>Mike Sullivan              | 5. Collection Date:<br>7-17-15                                                                                                                                                    |
| 6. Sample TAT:<br><input type="checkbox"/> 24 HR <input type="checkbox"/> 48 HR<br><input type="checkbox"/> 72 HR <input type="checkbox"/> 5 Day<br><input checked="" type="checkbox"/> Other Rush | 7. Building Name:<br>Barrington Student Union | 8. Sampling Areas:<br>Kitchen slop sink run | 9. Comments: (Field)<br><input checked="" type="checkbox"/> Analyze to First Positive By Homogeneous Material<br><input type="checkbox"/> For Negative NOB PLM's, continue to TEM |

[illegible]

| 20. Relinquished By: | 21. Date | 22. Time | 23. Received By: | 24. Date | 25. Time |
|----------------------|----------|----------|------------------|----------|----------|
| I Mike Sullivan      | 7-17-15  | 1600     | Robert DeLo      | 7/18/15  | 1600     |
| II                   |          |          |                  |          |          |
| III                  |          |          |                  |          |          |

**29. Ambient Project Manager:**

|                              |                |
|------------------------------|----------------|
| 29. Ambient Project Manager: | Joella Viscusi |
| 30. Results To:              | _____          |
| Phone #'s:                   | _____          |
| Fax:                         | _____          |

**31. Drawings:** ☐ Sample Locations  
☐ Material Locations

32: Comments: