



Tim 052709A- ENV AIR MON
Asbestos Air Sampling Analysis Report

Analyzed in accordance with
 NIOSH Method 7400 (A Rules)
 NYS DOH ELAP #11555

Client: SUNY College at Potsdam - 44 Pierre Pont Ave., Potsdam, NY 13676

Project Location: Timerman - Basement - Project #2 - Floor Tile/Mastic

Project Number: EL09A-7

Client Contact: Andy Martin

Phone Number: (315) 267-2135

Contractor: Op-Tech

Report Number: 1272

Date Sampled: 5-27-09

Date Received: 5-28-09

Date Analyzed: 5-28-09

Date Reported: 5-28-09

Summary: On May 27, 2008, our representative, Scott Landry, collected the following samples in accordance with all state and federal regulations.

Work Area Location	Sample Type	Elapsed Time Minutes	Flow Rate L/Min	Volume liters	Result f/mm ²	Result f/cc	Field ID	Lab ID
Ambient	E	140	2.0	280	<6.87	<0.009	1	8206
Critical Barrier #1	E	120	2.0	240	<6.87	<0.009	2	8207
Critical Barrier #2	E	120	2.0	240	<6.87	<0.009	3	8208
Personal Decon	E	120	2.0	240	<6.87	<0.009	4	8209
Waste Out	E	120	2.0	240	<6.87	<0.009	5	8210
Negative Air	E	140	2.0	280	<6.87	<0.009	6	8211
Field Blank	FB	NA	NA	NA	NC	NC	7	8212
Field Blank	FB	NA	NA	NA	NC	NC	8	8213

High or unusual results are highlighted and italicized.

ABBREVIATIONS:

B = Background Sample

PA = Pre - Abatement Sample

E = Daily Environmental Sample

F = Final Clearance Sample

WA = Work Area Sample

STEL/EL = Short Term Exposure/Excursion Limit Sample

P = OSHA Personal Air Monitoring Sample

FB = Field Blank

NC = Non-Contaminated

MD = Mineral Dust, Unable to Analyze

SD = Sample Damaged, Unable to Analyze

f/cc = Fibers Per Cubic Centimeter

f/mm² = Fibers Per Square Millimeter

< = Below Detection Limit

NS = Not Supplied

NA = Not Applicable

Valerie Lare

Approved By: Valerie Lare

Technical Director - Envirologic of New York, Inc.

Disclaimer: NIOSH Method 7400 is a method used for estimating asbestos concentrations, however, phase contrast microscopy cannot distinguish between asbestos fibers and other fiber types. The analytical results presented in this report and the laboratory procedures used are considered to be accurate and reliable for the samples analyzed. This report may not be reproduced without the approval of Envirologic New York, Inc., and then only in full. Envirologic of New York's liability is limited to the cost of the analysis.

Envirologic of New York, Inc.

Central Office: 6950 East Genesee Street, Fayetteville, New York 13066

Ph: (315) 455-2714 Fax: (315) 455-3022



6950 E. Genesee St. • Fayetteville, New York 13066 • Telephone (315) 455-2714 • Fax (315) 455-3022

PROJECT #: EL09A- 7

LAB REPORT #: 1272

Project Name/City/Project Info:	Floor Tile Timeman Basement Project ② Mastic		Client Name:	Sony Potsdam	
Date:	5-21-09	Contractor:	Op.Tech		
		Hygienist:			
		Client Address:	44 Pierrepont Ave		
		Contact:	Andy Martin	Potsdam, NY	
		Client phone #:			
		Client fax #:			
		Calibration:	9-14-09	Rotometer #:	E22

[illegible]

Sample Type: B = Background PA = Pre-Abatement E = Environmental WA = Work Area F = Final BL = Blank P = Personal EL = Excursion Limit

Chain of Custody	Print Name	Sign Name	24 Hour	48 Hour	72 Hour	Other:
Sampled By:	Scott Landry					
Relinquished By:	Scott Landry					
Received at Lab By:	KATIE CONGDON				5:28:09	1055
Turnaround Time:	RUSH (Specify):					

▶ Please contact the following individual(s) at the following number(s) with results.

▶ Please contact the following individual(s) at the following number(s) with results:

By signing above, I acknowledge that the data recorded on this form was collected by accurately following air-sampling procedures outlined in NYSDOL Industrial Code Rule 56 (12 NYCRR Part 56, Subpart 56-4, 56-6, 56-7.1, 56-8.1, 56-9.1, 56-10.1) and all other applicable state and federal regulations.